

1/12




FIG.1

2/12




FIG.2

3/12




FIG. 3




FIG. 4




FIG. 5

4/12




FIG.6

5/12




FIG.7

6/12




FIG.8




FIG.9

8/12




FIG.10

9/12






FIG.11




**AFTER CURRENT-VOLTAGE CONVERSION
WITH 10% STRAY LIGHT**

FIG.12

10/12



AFTER CURRENT-VOLTAGE CONVERSION
WITH 30% STRAY LIGHT

FIG.13**FIG.14**

11/12




FIG.15




FIG.16

12/12




FIG.17




FIG.18